

#### MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

**RECEIVED** 

By Carol Day at 3:15 pm, Nov 03, 2014

#### DATAMASTER MAINTENANCE REPORT

Complete this report at the time of the regular monthly preventive maintenance check (not to exceed 35 days). Complete this report whenever the instrument is serviced or repaired and whenever it is placed into service. Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS. NAME OF AGENCY DATE OF INSPECTION DATAMASTER SN **Directorate of Emergency Services** 202091 11/01/2014 TIME OF INSPECTION LOCATION OF INSTRUMENT (STREET AND CITY) 0721 Bldg 1000, Fort Leonard Wood CHECKLIST: Place a mark in the box by each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unmarked items must be corrected before using instrument. DATE AND TIME (from printout) 11/01/14 /072/ DIAGNOSTIC CHECK (PRINTOUT ATTACHED) DETECTOR **∇** COMPUTER 7 FILTERS PROGRAM 50 **▼** HEATERS SAMPLE CHAMBER 9 OUARTZ STANDARD CALIBRATION FLOW DETECTOR 7 PRINTER V PUMP HIGH SPEED INDICATOR LIGHTS EXP. DATE 01/09/2015 SIMULATOR SOLUTION SUPPLIER GUTH LABS INC LOT # 13010 EXP. DATE 10/20/2015 DR5376 34.0 SIMULATOR TEMP (34°C ± 0.2°C) °C SIMULATOR SN CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) ☑ 0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE 0,080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE O.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE TEST 3 e .105 TEST 2 . /0/ ./03 PERFORM R.F.I. TEST (PRINTOUT ATTACHED) INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS) **OVER .19** (.15 - .19)(.10-.14)REFUSALS D (.05-.09)(0-.04)LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS TESTED AND CERTIFIED AS WITHIN GUIDELINES ESTABLISHED BY DHSS. INSPECTING OFFICER PRINT FISH NAME SIGNATURE ROBERT ISHMAEL TELEPHONE NUMBER TYPE II PERMIT NUMBER/EXPIRATION DATE (573) 596-1074 230001 01/08/2015 Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office RETURN COMPLETED REPORT TO THE: 2875 James Blvd.

Poplar Bluff, MO 63901

# Face This Side Down - This Edge In First

### **BAC DataMaster Evidence Ticket**

HOUSE BEANDED LYNN THE M OF MERSHAN VIEW TO ME

THE DETERMINE SERIEL NUMBER COCKY

京文 一

SIL

THE DIMENSITY OF THE PARTY OF T

COMPLIFER

TROBERTY COA-OF-FEEDS:

TENTENCH TEN

ATTALE CHAPTER

1 [] 1 [] 1 []

SEX

FLOW DETECTOR:

TETEL TOP :

TITIES

OWNERS STANDARD:

7

9

SHITELEROPORO TO YOUNG TO BE SEED OF THE SECOND 「主義者が多一へしてす。」、「別人の記名もなどのので、「モノシのの話の目的目の

# Face This Side Down - This Edge In First

### BAC DataMaster Evidence Ticket

TOTAME AND DESCRIPTION OF SECTION OF ELECT LEGIPPIND WOOD

MAC DELINITIES SERIAL NUMBER OFFICE 17.617.4

上海域の名人が発生が一

EXPERTION DATE: 01/05/15 THE NAME OF SECOND

MISCELLANGUS DATE:

## MUNICAL NOTE NOTE

TANDARD TANDARD TANDARD	10 1/8 Page	SO TO THILLIES				
	i i i i i i i i i i i i i i i i i i i		=	î	*	

# Face This Side Down - This Edge In First

#### BAC DataMaster Evidence Ticket

DIVERS YOUR OF EMERGENCY SERVICE TOWN TRUINGS NOOT

MANAGE SECTION TO THE SECTION 23/82/14

COCHOL FIETH OF THE SIBJECT NEWE:

10%; 81/81/81

TO THE MAN THE SECOND

ATSELLAMENCE DATE:

THE THE THE TAIL 

WEST THE OFFICER

EXPIRATION DATE: SIVES PERMIT NUMBER: 230001

DUIL TA

PART TERM



## STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES
BREATH ALCOHOL PROGRAM
PERMIT



## TYPE II ROBERT ALAN ISHMAEL

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

## DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections 577.020 through 577.041, RSMo and 305.111 through 305.119 RSMo.

DATE	01/08/2013	We want
	230001	DIRECTOR OF STATE PUBLIC HEALTH LABORATORY
	01/08/2015	Acting Director
MO 580:0771 (6-10)		DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVI

LAB-4 (R6-10)



#### CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 13010 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography on January 14, 2013, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1218% (w/vol) ethyl alcohol. The expiration date for this lot number is January 9, 2015 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.